Update 9/6/2015

1. Reverse Q40 Emitter and Collector, Modify schematic as well Transistor reversed causing bypass pops

Update 4/28/13

1. Increase resistance of Phantom Iso R Change R311 from 10K 5/w to 334k

New Updates as of 04-13-13

1. Corrrect output stage power supply centering Add 4 18v zener diodes (1N4746A) across C181+C65

2. Change Output DC Servo parts values

Change R21 and R87 to 200k

Change C187 and C16 to u47/50-63v

Change R436 and R437 to 1k0

Change R31 and R33 from 1meg to 255k

- 3. Hook up missing ground from C114/C152 to CTL GndX Add jumper from C116/C133 to C114/C152
- 4. Change Fan Type to Noctua NF-R8
- 5. Correct Gain Cell bypass mute delay

Change Q40 from 2n5401 to MPSA77

Replace R205 with two 8k6 resistors

Change C7 from 22n to u47 and move top to midpoing between two 8.k resistors

- 6. Eliminate redundant parts from output stage PS Remove C150,R435,C173,R314
- 7. Correct meter TempCo

Change D79 and D509 from 1N270 to SD101 (Low drift

Shottkey)

Change D22 from 1N270 to 1N4148 Add 1n5819 (High drift shottky in series with R225

Updates and changes to be done to ALL BA-660's

- 1. Correct Gain Cell Drive: Install 25k pot and 20k0 Resistor From -24v to Cathode constant current driver of V3
- 2. Correct Output Metering: Change R107 from 4k99 to 4k23/12 ? (Choose by measurement.)
- 3. Correct Attack Current source gain: Change R284 from 22k1 to 2k21

4. Correct heat sensitivity: Replace D20, D25, D59 with 1n4148

5. Correct Clip light levels:

1st stage-Change R344 and R345 from 11k to 3k24

2nd Stage- Change R402 & R419 from 11k to 4k99

Add missing ground from Q36-3/Q38-2/Q37-2/Q39-2 to C113 minus

- 6. Verify bias point of 2nd stage@ U15-1 >-22&+22< Set with R38 249-255
- 7. Set Insert detect K7 to reliable switch New: Replace Q2 with 2n5401

Old: Find appropriate value for R56 to reliably turn on Q2 and NOT light LED!

8. Correct GC HF Rolloff

Add 47pf in parallel with R236 and R237

9. LF Roll Off

Add 100u/63v in parallel with C36 & C37

10. Reduce GC Meter non linearity

Change R278 from 2k4 to 1k3

11. Add GC Meter trim

Replace R225 with 100r0 25 turn pot

OLD UNITS ONLY

- O Remove Humidity induced distortions CONFORMALLY COAT MOTHER PCB TOP and BOTTOM
- 1. Improve GR Cathode pullup zener reliability Replace R160 with 100k 2 watt
- 2. Reduce GR Noise

Add 1u/35v Tant across Z13

## Z:\LIMITER\Updates and Changes\UPDATES\_09-6-2015.txt

Sunday, September 06, 2015 10:30 AM

3. Improve tip in adjustment range R18 from 10k to 15k

Change R6 from 15K to 33k, R453 from 15k to 39k,

4. Center Gain Control DC Ranges

Change R270 from 137k to 150k, Change R333 from 10k

to 27k

5. Remove OP Balance switch and Replace with Xformer

Remove Sw12, K11 and K12, U1 and


Install Jensen JT-11BM in at place of R26 and R32

MUCH older units

16. Improve GR Meter Zero

Add R89, R457, D30, D22 and change R280 to 20k





Q40 Fix

## UPDATES\_12-1-2012.txt

Updates and changes to be done to ALL BA-660's

1. Correct Gain Cell Drive: Install 25k pot and 20k0 Resistor From -24v to Cathode constant current driver of V3

2. Correct Output Level trim: Change R107 from 4k99 to 4k23/12 ? (Choose by

measurement.)

3. Correct Attack Current source gain: Change R284 from 221k to 22k1 4. Correct extreme heat sensitivity: Replace D20, D59 with 1n4148

5. Correct Clip light levels: 1st stage-Change R344 and R345 from 11k to

3k24

2nd Stage- Change R402 & R419 from 11k to

4k99

6. Verify bias point of 2nd stage@ U15-1 >-22&+22<

7. Set Insert detect K7 to reliable switch

for R56 to reliably turn on Q2 and NOT light LED!

8. Correct GC HF Rolloff

R236 and R237

9. Reduce Threshold adjustment drift

Set with R38 249-255

New: Replace Q2 with 2n5401

Old: Find appropriate value

Add 47pf in parallel with

Replace D25 with 1n4148

OLD UNITS ONLY

10. Remove Humidity induced distortions

TOP and BOTTOM

11. Improve GR Cathode pullup zener reliability watt

12. Reduce GR Noise

13. Improve tip in adjustment range

R453 from 15k to 39k, R18 from 10k to 15k

14. Center Gain Control DC Ranges

150k, Change R333 from 10k to 27k

15. Remove OP Balance switch and Replace with Xformer and Install Jensen JT-11BM in at place of R26 and R32

CONFORMALLY COAT MOTHER PCB

Replace R160 with 100k 2

Add 1u/35v Tant across z13 Change R6 from 15K to 33k,

Change R270 from 137k to

Remove Sw12, K11 and K12, U1

MUCH older units


16. Improve GR Meter Zero change R280 to 20k

Add R89, R457, D30, D22 and





## MotherBoard P1



## Gain Control PCB

