



REV	DESCRIPTION
00A	DWG# WAS FILED. 30-0023-00A WAS 5050-34
8-21-88 AD	001. REM. PAIR COLORS. UNUSED PAIR INFO. OTARI PIN DESIGNATIONS. LYNX LIFTER DEFEAT. PULLUPS ADDED. SOME '2 TEXT WAS '1. LYNX CTRL. COM GROUNDING PT. CHANGED FROM LYNX PIN 1. DISCRETE WIRE COLORS ADDED.
00B 9-20-88 AD	ADDED LYNX PIN 25 CONN.: ADD PLAY TALLY NOTE: CHANGED DWG.# WAS 30-0023-00B
1/10/90 BT	REMOVE PLAY TALLY NOTE: ADD CONN. TO PIN 31 AT MACH. (PLAY TALLY)

TEN PAIR CABLE UNUSED PAIRS:  
RED (WHT) AND WHITE (RED)

(C) 1989 TIMELINE, INC. 270 Lafayette St. New York, N.Y. 10012		APP'D
SCHEMATIC CABLE ASSEMBLY OTARI 5050 MK III-34		CHK'D
CONFIDENTIAL	DATE	1/10/90
DWG 70D028-20	REV D	PAGE 1
	SIZE B	